



## **APPLICATION – SAFETY & HANDLING**

- PROTECTIVE EYEWEAR AND GLOVES ARE RECOMMENDED WHEN HANDLING OR APPLYING
- DO NOT APPLY THE COATING IN HOT, DIRECT SUNLIGHT OR IF GLASS SURFACE TEMPERATURE IS IN EXCESS OF 90°F OR BELOW 32°F.
- DO NOT APPLY ON WET, RAINY DAYS OR WHEN THE HUMIDITY IS ABOVE 90%

## **SPRAY OR WIPE ON APPLICATION INSTRUCTIONS:**

- SPRAY PRODUCT DIRECTLY AND EVENLY ONTO CLEAN GLASS SURFACE USING A FINE MIST SPRAYER
- HOLD SPRAYER APPROXIMATELY 6-9” FROM GLASS - CLOSER MAY CAUSE PRODUCT RUNOFF
- MAKE SURE THE GLASS IS VISIBLY WET WITH PRODUCT
- AFTER SPRAYING A FINE MIST USE MICROFIBER STICK OR CLEAN CLOTH TO SPREAD PRODUCT EVENLY

### **6”- 9” AWAY FROM GLASS**



### **SPREAD EVENLY**



- **CLOTH OR MICROFIBER STICK CAN BE CONTINUALLY REUSED FOR APPLICATION. MUST REMAIN CLEAN & UNCONTAMINATED BY SOIL OR OTHER CHEMICALS INCLUDING WATER.**
- ALLOW THE PRODUCT TO DRY ON THE GLASS (2-3 MIN.) OR UNTIL EVAPORATED
- ALLOW THE COATING TO DRY UNTIL A SLIGHT HAZE
- RE-APPLY A 2<sup>ND</sup> COATING TO ENSURE COMPLETE COVERAGE IF NECESSARY
- REMOVE ANY EXCESS HAZE BY SPRAYING OR RINSING THE GLASS WITH CLEAN WATER
- DRY WITH COTTON/MICROFIBER OR PAPER TOWEL (TOOL) UNTIL CRYSTAL CLEAR

## **QUALITY CONTROL:**

- TO TEST GLASS FOR WATER REPELLENCY, SPRAY MIST OF WATER. YOU WILL SEE SMALL ROUND WATER DROPS WITH A CONTACT ANGLE ABOVE 108°
- **STORAGE & SHELF LIFE** - INVISIBLE SHIELD PRO 15 GLASS COATING CONTAINS A FLAMMABLE SOLVENT AND SHOULD NOT BE USED OR STORED NEAR AN OPEN FLAME OR AT TEMPERATURES ABOVE OR 113°F. STORE AWAY FROM DIRECT SUNLIGHT, IN A COOL DRY PLACE. SHELF LIFE OF INVISIBLE SHIELD PRO 15 IS INDEFINITE IN CLOSED CONTAINERS.

- **POISON CONTROL - ChemTel: 1-800-255-3924**